**Property Inspection Report** 



1600 Anywhere, Beaverton, OR 97007 Inspection prepared for: John Doe Date of Inspection: 5/1/2019 Time: 1:00 pm Age of Home: Built 2017 Size: 3127 sq ft Weather: Overcast

Inspector: Don Grossarth CCB #204194, OCHI #1736 1527 Maple Street, Forest Grove, OR 97116 Phone: 503-881-7031 Email: oregonnwhomes@gmail.com oregonnwhomes.com

THIS REPORT IS INTENDED ONLY FOR THE USE OF THE PERSON PURCHASING THE INSPECTION SERVICES. NO OTHER PERSON, INCLUDING A PURCHASER OF THE INSPECTED PROPERTY WHO DID NOT PURCHASE THE INSPECTION SERVICES MAY RELY UPON ANY **REPRESENTATION IN THE REPORT.** IF A RED ARROW OR CIRCLE IS SHOWN, I WOULD LIKE TO CALL YOUR ATTENTION TO AN AREA. A GREEN ARROW OR CIRCLE, NO ISSUE.

#### **Report Summary**

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expenses to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all of the pages of the report as the summary alone does not explain all the issues. All repairs must be done by a licensed &bonded trade or profession. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

#### Bathroom

Page 15 Item: 4 Counters

• Caulk or grout at/or behind sinks and master tub as needed.



Caulk or grout at/or behind sinks and master tub as needed.

Page 16 Item: 5 Doors	Door hardware needs adjusted at upstairs hall closet door.
Door hardware	needs adjusted at upstairs hall closet door.
Page 19 Item: 17 Bath Tubs	Caulk at base of tub spout.

Kitchen		Caulk at base of tub spout.
Page 22 Item: 4	Counters	Caulk/Grout is needed at kitchen backsplash. Caulk as needed.
	Caulk/Grout is need	ded at kitchen backsplash. Caulk as needed.
Heat/AC		
Page 30 Item: 4 Page 31 Item: 11	Filters Venting	<ul><li>Furnace filter dirty. Needs replacement.</li><li>Recommend cover on exterior intake to prevent wildlife from</li></ul>



Recommend cover on exterior intake to prevent wildlife from entry.

Garage						
Page 36 Item: 9	Garage Door's Reverse Status	• The door requires a great deal of resistance to trigger the auto-reverse mechanism. We recommend adjusting the opener for proper reverse tension.				
Roof						
Page 38 Item: 1Roof Condition• Roof anchors covers are not in place. This can lead to ru on the anchors. Recommend roof anchor covers are place over anchors.						
Roof anchors co		e. This can lead to rust on the anchors. Recommend roof anchor overs are placed over anchors.				



Roof vent on left side of structure appears loose and pulling away. Recommend repair.

Exterior Areas						
Page 45 Item: 3	Exterior Paint	<ul> <li>Peeling paint observed on trim. suggest scraping and painting as necessary.</li> </ul>				
Peeling paint obs	served on trim. sugge	est scraping Peeling paint observed on trim. suggest scraping				

Peeling paint observed on trim. suggest scraping Peeling paint observed on trim. suggest scraping and painting as necessary.

Page 45 Item: 4	Siding Condition	<ul> <li>Recommend flashing over decorative beams to prevent Decay.</li> </ul>
-----------------	------------------	--

	Decommond flock	The over decertive beams to provent Decay
Croundo	Recommend hashi	ng over decorative beams to prevent Decay.
Grounds Page 52 Item: 7	Gate/Fence Condition	Posts is loose at gate. Recommend repair.
		Ioose at gate. Recommend repair.
Page 54 Item: 14	Vegetation Observations	• Recommend a 12" to 18" area around the foundation, clear of vegetation.
	·	



Recommend a 12" to 18" area around the foundation, clear of vegetation.

We appreciate the opportunity to conduct this inspection for you! Please carefully read your entire Inspection Report. Call us after you have reviewed your report, so we can go over any questions you may have. Remember, when the inspection is completed and the report is delivered, we are still available to you for any questions you may have, throughout the entire closing process. Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible portion of the structure; inspection may be limited by vegetation and possessions. Depending upon the age of the property, some items like GFI outlets may not be installed; **this report will focus on safety and function, not current code**. This report identifies specific noncode, non-cosmetic concerns that the inspector feels may need further investigation or repair. For your safety and liability purposes, we recommend that licensed contractors evaluate and repair any critical concerns and defects. Note that this report is a snapshot in time. We recommend that you or your representative carry out a final walk-through inspection immediately before closing to check the condition of the property, using this report as a guide.

# **Inspection Details**

1. Attendance
---------------

In Attendance: Buyer Agent present • Client present

2. Home Type

Home Type: Single Family Home

3. Occupancy

Occupancy: Occupied - Furnished

**Interior Areas** 

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.

	01130	meu	ii ye		
1. C	eilin	g Co	onditi	ion	
Good X	Fair			None	<sup>*</sup> Materials: Drywall ceilings noted. Observations: • Nail pops noted at upper level ceiling area.





## 1600 Anywhere, Beaverton, OR



#### 9. Screen Doors Good Fair Poor N/A



## 10. Smoke Detectors

Good Fair Poor N/A None	Observations
X	Observations: • State of Oregon requires that there is a smoke detector on each level of the home (including basement), one in each bedroom and a CO alarm within 15 feet of bedroom doors. Oregon also requires that alarms over 10 years old be replaced. http://www.oregon.gov/osp/sfm/pages/commed_sa_program.aspx
	<ul><li>This home meets these requirements.</li><li>Properly in place and functional.</li><li>CO detectors in place and responded well.</li></ul>
11. Stairs & Handrail	
Good Fair Poor N/A None	Observations: • Railing in place and functional.



12. Wall Condition
Good Fair Poor N/A None Materials: Drywall walls noted.
13. Window Condition
Good       Fair       Poor       NA       None         X       Image: Materials       Vinyl framed single hung window noted.       • Vinyl framed sliding window noted.         X       Image: Materials       • Vinyl framed single hung window noted.       • Vinyl framed sliding window noted.



#### Bedrooms

The main area of inspection in the bedrooms is the structural system. This means that all walls, ceilings and floors will be inspected. Doors and windows will also be investigated for damage and normal operation. Personal items in the bedroom may prevent all areas to be inspected as the inspector will not move personal items.

1. Locations


#### Locations: Master • Upstairs Right rear • Upstairs Left rear

## 2. Ceiling Condition



Materials: There are drywall ceilings noted.


#### 3. Closets







4. Doors
Good Fair Poor N/A None
5. Electrical
Cood Fair Roor N/A Nono
X       Observations:         • Some outlets not accessible due to furniture and or stored personal items.
6. Floor Condition
Good Fair Poor N/A None Flooring Types: Carpet is noted.
X Observations:
Stored items limited floor inspection in bedrooms.
7. Smoke Detectors
X       • State of Oregon requires that there is a smoke detector on each level of the home (including basement), one in each bedroom and a CO alarm within 15 feet of bedroom doors. Oregon also requires that alarms over 10 years old be replaced.         http://www.oregon.gov/osp/sfm/pages/commed_sa_program.aspx         • The smoke detectors operated during the inspection.
8. Wall Condition
Good Fair Poor N/A None Materials: Drywall walls noted.







## 9. Window Condition

Good	Fair	Poor	N/A	None
Х				

Materials: Vinyl framed sliding window noted. • Vinyl framed single hung window noted. • Vinyl framed fixed window noted.



#### Bathroom

Bathrooms can consist of many features from jacuzzi tubs and showers to toilets and bidets. Because of all the plumbing involved it is an important area of the house to look over. Moisture in the air and leaks can cause mildew, wallpaper and paint to peel, and other problems. The home inspector will identify as many issues as possible but some problems may be undetectable due to problems within the walls or under the flooring..

#### 1. Locations

Locations: Main floor half bath • Master Bathroom • Upstairs hall bathroom

## 2. Cabinets

Good	Fair	Poor	N/A	None	Ohaamatianaa		
Х					Observations: • Appeared functional and in	satisfactory condition, at time of insp	ection.
Sold in a	and and	1	X	Chi.rus			




#### 3. Ceiling Condition

None

Good	Fair	Poor	N/A
Х			


Materials: There are drywall ceilings noted.

#### 4. Counters





Caulk or grout at/or behind sinks and master tub as needed.





#### 9. Exhaust Fan



Observations:

The bath fan was operated.
Recommend fans be ran 25 minutes after shower or bath, to remove moisture from air that can cause moisture issues.

## 10. Floor Condition

Good	Fair	Poor	N/A	None	Materiale. Operational is in a tool. Election leaving to the officer in the d
					Materials: Ceramic tile is noted. • Floating laminate type flooring noted.
					Materials: Ceramic tile is noted. • Floating laminate type flooring noted.



None



11. Heating




Observations:

• Central heating noted in this room. At the time of the inspection, all appeared to be functioning and in serviceable condition.

#### 12. Mirrors









Caulk at base of tub spout.

## 18. Toilets

Good Fair Poor N/A None


Observations: • Observed as functional and in good visual condition.



# 19. Window Condition


Good	Fair	Poor	N/A
Х			

Materials: Vinyl framed single hung window noted. • Vinyl framed fixed window noted.



## 20. Walls

Good	Fair	Poor	N/A	None	
					Observ
Х					• Drywa



Page 20 of 56

#### Kitchen

The kitchen is used for food preparation and often for entertainment. Kitchens typically include a stove, dishwasher, sink and other appliances.

## 1. Cabinets

Good	Fair	Poor	N/A	None	$\sim$
X					•

Observations: • Appeared functional and in satisfactory condition. Random drawers and cabinet doors are checked.



## 2. Ceiling Condition

Х


Fair Poor N/A None Materials: There are drywall ceilings noted.

## 3. Cook top condition

Good	Fair	Poor	N/A	None	Observations
					Observations:
					• Gas cook top noted.



Gas cook top noted.



## 1600 Anywhere, Beaverton, OR



#### 7. Electrical



## 8. GFCI

Good	Fair	Poor	N/A	None	Observations
х					Observations: • GFCI in place and operational.

## 9. Floor Condition

Go	boc	Fair	Poor	N/A	None	Materiala, Election la volución de truca fla enire y setect
						Materials: Floating laminate type flooring noted.
	x					



#### 10. Microwave Fair

Poor

N/A

Good


Х

None

Observations: • Functional at the time of inspection.



# 11. Oven & Range



Observations: • Oven(s) operated when tested.



Oven(s) operated when tested.

12. Plumbing	
Good     Fair     Poor     N/A     None       X	
13. Sinks	
Good     Fair     Poor     N/A     None       X	
	Page 24 of 56

## 1600 Anywhere, Beaverton, OR



#### 14. Soap Dispenser Good Fair Poor N/A Non



# 15. Spray Wand

Good	Fair	Poo
Х		

Observations:

• The spray wand was operated and was functional.

## 16. Refrigerator

Good	Fair	Poor	N/A	None	Observations
Х					Observations: • Appears functional.
					<ul> <li>Water dispenser was functional.</li> <li>Ice maker was functional.</li> </ul>



## 17. Vent Condition



Materials: Exterior Vented Observations: • Exhaust fan is operational.

18. Wall Condition
Good       Fair       Poor       N/A       None         X       Image: A straight of the strain straight of the straight of the strain s
19. Window Condition
X Materials: Vinyl framed sliding window noted. Observations: • Operated windows appeared functional, at time of inspection.
Laundry
1. Ceiling Condition
X None Materials: There are drywall ceilings noted.
Sood     Fair     Poor     N/A     None       X     I     I     I

3. Dryer Vent
Good Fair Poor N/A None X Observations: • Could not fully inspect the dryer vent, it is not fully accessible at this location.
4. Electrical
Good     Fair     Poor     N/A     None       X
5. GFCI
Good     Fair     Poor     N/A     None       X     I     I     I
6. Exhaust Fan
Good       Fair       Poor       N/A       None         X       Image: Appeared functional, at time of inspection.       • Appeared functional, at time of inspection.         • Exhaust fan appears to be a unit that runs 24/7.
7. Floor Condition
X Poor N/A None Materials: Sheet vinyl flooring is noted.

## 1600 Anywhere, Beaverton, OR



## 8. Plumbing



All visible plumbing appears functional. Visually checked only.Utility sink is functional.



Observations:



All visible plumbing appears functional. Visually checked only.

#### 9. Wall Condition



## 10. Window Condition



Materials: Vinyl framed single hung window noted.


#### Heat/AC

The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at

Page 28 of 56

a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

For a more thorough investigation of the system please contact a licensed HVAC service person.



## 1600 Anywhere, Beaverton, OR



Appears functional. Recommend an HVAC contractor perform annual system cleaning and service. HVAC systems require regular maintenance.



## 4. Filters



# 5. Furnace Condition Good Fair Poor N/A None Materials: The furnace is located in the garage Materials: Gas fired forced hot air. 6. Gas Valves

Poor	N/A	None	
			Observations:

• Gas shut off valves were present and appear functional.

#### 7. Heater Base

Fair

Good

Х

Good	Fair	Poor	N/A	None	Observations
Х					<ul><li>Observations:</li><li>The heater base appears to be functional.</li></ul>



8. R	efrig	eran	t Lin	ies
Good	Epir	Poor	NI/A	Nono

0000	i ali	1 001	NULLE
Х			



#### 9. Registers

Good	Fair	Poor	N/A	None
Х				

## 10. Thermostats

Good	Fair	Poor	N/A	Non
Х				

- Observations:
- Furnace responded well to thermostat.Digital programmable type.

## 11. Venting

Good	Fair	Poor	N/A	N
x				


- Observations:
- Plastic PVC vent noted.
  The visible portions of the vent pipes appeared functional.
  Recommend cover on exterior intake to prevent wildlife from entry.




Recommend cover on exterior intake to prevent wildlife from entry.



Plastic - PVC vent noted.





Page 33 of 56



## 9. TPRV





Observations: • A pressure & temperature relief valve & extension is present and appears satisfactory.



10. Venting
Good Fair Poor N/A None
Garage
1. Exterior Door
X Poor N/A None Observations: • Appeared functional, at time of inspection.
2. Fire Door
Good       Fair       Poor       N/A       None         X       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Y       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A

Page 34 of 56





#### 8. Garage Opener Status

••••									
Good	Fair	Poor	N/A	None	Observations:				
					Observations:				
<u> </u>					• The garage door opener is functional, safety features are built in.				
9. Garage Door's Reverse Status									
Good	Good Fair Poor N/A None Obcorructions:								

#### Observations:

• Eye beam system present and operating.

• The door requires a great deal of resistance to trigger the auto-reverse mechanism. We recommend adjusting the opener for proper reverse tension.

#### 10. Rafters & Ceiling

N/A

None

	Good	Fair	Poor
ſ	Х		

Х

Observations: • Visible areas appear satisfactory, at time of inspection.



11.	Walls	
Good	Fair	Р

Good

Х

N/A Poor None Observations:

Appeared satisfactory, at time of inspection.Stored personal items in garage limit inspection of floor and walls.

12. Anchor Bolts
• The anchor bolts were not visible.
Electrical
1. Electrical Panel
Good       Fair       Poor       N/A       None         X       Location:       Main Disconnect in panel box.       Panel box located in garage.
2. Breakers Good Fair Poor N/A None X Materials: Copper non-metallic sheathed cable noted.



## 3. Cable Feeds

Good	Fair	Poor	N/A	None	
					Observations:
X					• There is an underground service lateral noted.


4. Main Amp Breaker         Good       Fair       Poor       N/A       None         X       Image: Second Fair       Observations:       • 200 amp         5. Breakers in off position       Observations:       • 0         Good       Fair       Poor       N/A         X       Image: Second Fair       Observations:         • 0       • 0
Roof
1. Roof Condition
Cood       Fair       Poor       N/A       Nome         X       Image: Second Seco




Roof anchors covers are not in place. This can lead to rust on the anchors. Recommend roof anchor covers are placed over anchors.



Attic




5. Exhaust Vent
X Observations: • Functional.
X     · Functional. • Properly vented to exterior of structure.
Properly vented to exterior of structure.
6. Insulation Condition
Good       Fair       Poor       N/A       None         X       Image: Second stress of the seco
<image/>
Ored Feir Deer N/A Neve
Coor     Pair     Poor     N/A     None       X     Image: Appears structurally sound.



## 1600 Anywhere, Beaverton, OR



#### 9. Vent Screens



Exterior /	Areas
------------	-------

1. Doors Good Fair

Х

Observations: • Appeared in functional and in satisfactory condition, at time of inspection.

## 2. Eaves & Facia

Poor

N/A

None

None



Observations: • Appears functional.



Good	Fair	Poor	N/A	None	Observations: • All exterior painted wood trim surfaces should be annually examined and sealed, re-caulked and re-painted as needed.
					• Peeling paint observed on trim. suggest scraping and painting as necessary.
120	1 152	A CONTRACTOR			





Peeling paint observed on trim. suggest scraping Peeling paint observed on trim. suggest scraping and painting as necessary.

and painting as necessary.

### 4. Siding Condition

Good	Fair	Poor	N/A	None
Х				

Materials: Composition cement siding ("Hardi-Plank" Type), wood frame construction, concrete foundation • Stone veneer noted. Observations:


- Appears functional.
- Recommend flashing over decorative beams to prevent Decay.







#### Recommend flashing over decorative beams to prevent Decay.





#### 4. Electrical, Foundation




#### 5. Ventilation

Good	Fair	Poor	N/A	None	Observations
					Observations:
					• Passive radon vent noted.



Passive radon vent noted.






#### 7. Access Panel

None



Observations: • Interior access panel installed and functional during the inspection.



### 8. Insulation

Good	Fair	Poor	N/A	None
Х				

Observations: • Subfloor insulation noted. Appears functional. Limits view of subfloor.


## 1600 Anywhere, Beaverton, OR



None



# 9. Moisture Barrier



Observations: • In place and functional.





In place and functional.

# 10. Post and PiersGoodFairPoorN/A

Х

N/A None Observ

Observations: • Concrete piers/wood posts support floor above.

# 1600 Anywhere, Beaverton, OR



## 11. Plumbing, Foundation


11. Plumbing, Foundation
Good       Fair       Poor       NA       None         X       Image: Supply Plumbing noted.       **SUPPLY**         Pex type supply plumbing noted.       **DRAIN, WASTE, VENT**         "ABS"       (Acrylonitrile-Butadiene-Stryrene) waste and vent pipes noted.         **OBSERVATIONS**       Appears Functional at time of inspection.         Image: Supple suppl
12. Sub Flooring         Good       Fair       Poor       N/A       None         X       Observations:       • Not fully visible for inspection due to subfloor insulation
13. Walls, Foundation         Good       Fair       Poor       N/A       None         X       Observations:         • Walls appear functional.



Walls appear functional.
14. Walls, Cripple
Good Fair Poor N/A None
Grounds
1. Deck
Good Fair Poor N/A None
2. Stairs & Rails
Good Fair Poor N/A None
3. Driveway and Sidewalk Condition
Good       Fair       Poor       N/A       None         X       A       Materials: Concrete driveway noted.       Concrete sidewalk noted.         Observations:       • Sidewalk is in good condition.       • Sidewalk is in good condition.         • Driveway in good condition.       • Driveway in good condition.

4. Grounds Electrical
Good       Fair       Poor       N/A       None         X       Image: Second Seco
5. GFCI
Good       Fair       Poor       N/A       None         X       Observations:       • GFCI in place and functional.
6. Exterior Faucet Condition
X Deservations: • Appears Functional.
7. Gate/Fence Condition
X A None X A None Observations: • Posts is loose at gate. Recommend repair.
Posts is loose at gate. Recommend repair.

8. Grading		
Good       Fair       Poor       N/A       None         X       Observations:       • Lot grading and drainage have a significant impact on the building because of the effect that moisture can have on the foundation. It is important that surface runoff water be adequately diverted away from the home. ideally, lot grading should slope away and fall one inch every foot for a distance of five feet around the perimeter of the building.		
9. Main Gas Valve Condition		
Good       Fair       Poor       N/A       None         X       Image: Solution of the second state of t		
10. Balcony		
Good Fair Poor N/A None X X X		
11. Patio		
Good       Fair       Poor       N/A       None         X          Observations:         • Slab is in good condition.		



	rood Anywhere, Dedverten, er
15. Water Pressure	
Good       Fair       Poor       N/A       None         X       Image: Solution of the second se	
16. Main Water Shut Off	
Good       Fair       Poor       NA       None         X       I       I       Observations:       • Located in the garage.         • Located in the water meter box.       • Located in the water meter box.	

## Glossary

Term	Definition
ABS	Acronym for acrylonitrile butadiene styrene; rigid black plastic pipe used only for drain lines.
GFCI	A special device that is intended for the protection of personnel by de-energizing a circuit, capable of opening the circuit when even a small amount of current is flowing through the grounding system.
PVC	Polyvinyl chloride, which is used in the manufacture of white plastic pipe typically used for water supply lines.